Bruhath Bangalore Mahanagara palike,

Inspection Report

1	Name of work	Construction of Bridge over Storm Water Drain at 5th Cross Road and 12th A Main Road Mutyala Nagara in JP Park Ward No.17
2	Administration Approval & Date	JC/RRN/AS/2802/13-14 Dtd 18/01/2014 by JC (RRN)
3	Technical Sanction Estimate No. & Date	EE/RRND/TS/286/13-14 Dtd:18/01/2014 by EE (RRND)
4	Estimate Amount	Rs.19.99 Lakhs
5	Job Code No.	017-14-000096
6	P-Code	P2434
7	Agreement No & date	EE/RRND/AG No./254/2013-14 Dtd.20-02-2014
8	Work order Number & Date	EE/RRND/W.O/254/2013-14 Dtd.20-02-2014
9	Contract Amount as per Agreement	Rs.20,83,676/-
10	Bill Amount	Rs.20,69,107/-
11	B.R. No. & Date	66/2015-16 dt.31-07-2015
12	Agency	M/s. J.C.Prakash
13	M.B. Number & Page No. of Measurement recordes	174/2013-14 Pages to 17332 to 17339
14	Date of Inspection	30-05-2016
15	Enclusures	1) Extract of MB No.174/13-14 Page ~~17340~~ 17340 2)4 Number of photos taken during inspection of above site.
16	Inspection Report	I have Inspected the above site Location along with the Concerned person The measurment of the Items which are suceptible for measurments have been checked and found to be satisfactory

Raeshreedas

EE (RRND) RR Nagara

30/5/2016

(R.Sathyanarayana)
Inspection Report officer,

Scanned by CamScanner